INACTIVE STATUS
61-21368-13 now replaced by 61-21368-13 which has valve cap, core, preinstalled.
02/10/03 L.S.

☒ Converted Part ☐ Second Source Part NO. 237

YES ☒ NO ☐ DATE 6/15/82 REV. B

P/N 61-21368-13 IBM 83-03-393
DESCRIPTION Valve Bracket Kit
SET-UP BY D. PALMATARY APPROVED BY
DATE 6/28/85

PART HISTORY

SALES _____ (for Rolling Year)
TOTAL ON HAND _____
FS ____ MV ____ GV ____
Branches: LV ____
CL ____ PX ____ TS ____

PARTS USED IN CONVERTING PART

1) (1) P/N 61-21368-03 DESC Brass Valve
83-03-367
2) (1) P/N AE-56389-02 DESC Mounting Bkt
03-09-172
3) (1) P/N 61-18551-01 DESC Valve Core (✓)
83-03-924
4) (1) P/N 83-17071-01 DESC Valve CAP
83-37-385
5) P/N -069 DESC Stuff
6) P/N 92-21398-01-04 DESC WAP ▲

▲ Added this Rev.

PARTS TO BE MADE AT THIS TIME _____
WITH THESE INSTRUCTIONS DATE
per _____ LS BT BH DP
NUMBER DATE
ICE

"INACTIVE STATUS"
DATE 7/12/89 BY L. STEC REVISION C
REPLACED BY PART NO. 61-21368-83
ON PCF 476.
IF THIS PCF IS NEEDED IN THE FUTURE SEE PARTS ENGINEERING.

STATUS
ONE TIME ONLY ☐ *
TEMPORARY ☐ *
PERMANENT ☒
* Init. Req At Time of Build
DATE _____

WAREHOUSE REPRESENTATIVE SIGNATURE _____
JC BR BH

LABEL

STANDARD LABEL ☐
SPECIAL LABEL ☒ •

NEW DN _____
(if Applies)

SPECIAL INSTRUCTIONS

(✓) Valve Core, 61-18551-01, and Valve Cap, 83-17071-01, will be packed in an envelope, then stapled shut.

(*) Instruction tag 92-21398-01-04 has a hole which must be slipped over hex nut on top of the valve. (Hole must be slit for larger values.)

☐ YES ☒ NO See _____ For Special Instructions/Handling

1 Expedited Order, Need to ship ASAP
2 EMERGENCY
3 ONLY practical method of having (NLA) part
4 Lead Time Not Acceptable
5 Quantity purchase does not allow buying part
6 Stock Rework or Kit

• SPECIAL LABELS Should be Kept for future Reference
* SEE BOB T. DON P. FOR INSTRUCTIONS BEFORE BUILDING ANY FUTURE CONVERSIONS OF THIS PART

CC M. BURCHAM
J. FITCH
B. HILTS
L. SHARP
J. CRAWFORD

12-13-84 DS